

June 2011 FISHWAY INSPECTION SUMMARY

Fishway Inspections were conducted at most Columbia and Snake River Dams fitted with adult fish passage structures over June of 2011.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

Bonneville Dam (June 10, 2011): Washington Shore entrance weir elevations and head differentials below criteria.

Ice Harbor Dam (June 28, 2011): North Shore weir cable broken at NEW-1, weir on sill (cable found broken on June 23, 2011).

Little Goose Dam (June 29, 2011): The North Shore fishway off limits due to erosion damage that occurred in May, readings obtained from FC Board.

Lower Granite Dam (June 30, 2011): Low ladder weir depth (0.8 ft). NSE-1 weir is manually positioned due to broken cable.