

OCTOBER 2009 FISHWAY INSPECTION SUMMARY

Fishway Inspections were conducted at all thirteen Columbia and Snake River Dams fitted with adult fish passage structures over October of 2009.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

Ice Harbor Dam (October 20, 2009): NEW1 below criteria and gate not on sill.

Lower Monumental Dam (October 20, 2009): North and South shore exits needed some cleaning.

Priest Rapids Dam (October 29, 2009): Velocity in collection channel below criteria due to malfunctioning diffuser valve.