

Table 9. Pertinent Data for Fish Facility Inspections in 2008 at PRIEST RAPIDS DAM.

CRITERIA ITEMS	DATE OF INSPECTION							
	24-Apr	22-May	26-Jun	24-Jul	28-Aug	18-Sep	24-Oct	
LEFT BANK FISHWAY								
<i>Left Bank Entrance:</i>								
Head at main entrances (Criteria = 1-2 ft)								
LSE-2 (1.2 ft target)	ft	1.4	1.5	1.7	1.7	1.2	1.4	1.5
LSE-4 (1.5 ft target)	ft	1.5	1.2	1.1	1.6	1.6	1.5	1.5
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.1	1.0	1.1	1.0	1.1	1.1	1.0
Water velocity (Crit. = 1.5-4 fps)	fps	>1.5	2.4	2.2	2.0	1.9	1.8	1.7
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
RIGHT BANK FISHWAY								
<i>Right Bank Entrance:</i>								
Head at Entrance (Criteria = 1-2 ft)								
RSE-1 (1.5 ft target)	ft	1.3	1.4	1.5	1.5	1.3	1.4	1.5
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.1	1.1	1.1	1.2	1.2	1.2	1.1
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
Comment number (if applicable)		1	2	3				4
Comments:								
1. One aux. Pump is inoperative due to needed maintenance								
2. GIG no longer functions automatically- GCPUD is working on a fix.								
3. GIG still set in fixed position, velocity meter not working (visually estimated).								
4. GIG fixed but leaking some hydraulic fluid from RAM.								