

April 2011 FISHWAY INSPECTION SUMMARY

Fishway Inspections were conducted at most Columbia and Snake River Dams fitted with adult fish passage structures over April of 2011.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

McNary Dam (April 14, 2011): Some debris at Washington Shore ladder exit.

Little Goose Dam (April 12, 2011): Slightly low head differential at NSE (0.9 ft).